

SANWA-SEIKI VALVES

<p>Relay Valve</p> <p>JV9260S Top control, 1 delivery Metric ports U.D. - Various</p> <p>Repair Kit - JSK 33</p>			<p>Relay Valve</p> <p>JV9240S Top control, 2 delivery Metric ports Hino - Various</p> <p>Repair Kit - JSK 33</p>
<p>Relay Valve</p> <p>JV9210S Side control, 1 delivery Metric ports - Hino</p> <p>Repair Kit - JSK 33</p>			<p>Relay Valve</p> <p>JV9200S Side control, 2 delivery Metric ports - Hino</p> <p>Repair Kit - JSK 33</p>
<p>Relay Valve</p> <p>JV9280S Dual control, 2 delivery NPT ports - U.D.</p> <p>Repair Kit - JSK 33</p>			<p>Foot Valve</p> <p>JV5095S Old U.D. CW50 5 sided mounting</p> <p>Repair Kit - JSK 18.9</p>
<p>Foot Valve</p> <p>JV5060S</p> <p>Hino - most models</p> <p>Repair Kit - JSK 19</p>			<p>Foot Valve</p> <p>JV5080S</p> <p>Hino LB500 & LB560</p> <p>Repair Kit - JSK 19.4</p>
<p>Foot Valve</p> <p>JV5085S</p> <p>Hino - Various</p> <p>Repair Kit - JSK 19</p>			<p>Foot Valve</p> <p>JV5090S</p> <p>Hino - GH series</p> <p>Repair Kit - JSK 19</p>

SANWA-SEIKI VALVES

<p>Check valves</p> <p>Straight - 44510 1090</p> <p>90 degree - 44510 1190</p>	 <p>Straight 90 Degrees</p>		<p>Governor Valve</p> <p>44530 1160</p> <p>44530 1170</p> <p>Hino</p> <p>Repair Kit -N/A</p>
<p>Governor Valve</p> <p>44530 1311</p> <p>Hino</p> <p>Repair Kit - N/A</p>			<p>Governor Valve</p> <p>MC802149</p> <p>Isuzu / Mitsubishi</p> <p>Repair Kit - N/A</p>
<p>Hand Control Valve</p> <p>JV4000S</p> <p>Mitsubishi - various</p> <p>Repair Kit - JSK 52.1 JSK 52.9 JSK 52.91</p>			<p>Hand Control Valve</p> <p>JV4200S</p> <p>Hino FF</p> <p>Repair Kit - JSK 52 JSK 52.9 JSK 52.91</p>
<p>Hand Control Valve</p> <p>JV4210S</p> <p>Isuzu - Various</p> <p>Repair Kit - JSK 52.1 JSK 52.9 JSK 52.91</p>			<p>Hand Control Valve</p> <p>JV4220S</p> <p>Isuzu - Various</p> <p>Repair Kit - JSK 52.1 JSK 52.9 JSK 52.91</p>
<p>Hand Control Valve</p> <p>JV4260S</p> <p>U.D. - Various</p> <p>Repair Kit - JSK 52.1 JSK 52.9 JSK 52.91</p>			<p>Hand Control Valve</p> <p>JV4270S</p> <p>U.D. - Various</p> <p>Repair Kit - JSK 52.1 JSK 52.9 JSK 52.91</p>